


EXPLODED DIAGRAM

POWERTEC®



Part	Description	QTY
1	Upright	1
2	Adjusting tube	2
3	PVC sleeve	2
4	Handle tube	2
5	Weight tube	2
6	PVC sleeve	2
7	Foam	2
8	Bushing	2
9	Bushing	4
10	Square inner plug	8
11	Round inner plug	2
12	Screw	4
13	Washer	8
14	Nylon nut	4
15	Square inner plug	1
16	Screw	6
17	Cover	6
18	Powder metallurgy	8
19	Round inner plug	2
20	Screw	2
21	Collar	2
22	Shoulder pad	1

WB-PFA10

WORKBENCH PAC FLY ACCESSORY